## HISTORIC AMERICAN ENGINEERING RECORD

HAER PA 15-PHDEN 4C-

## **INDEX TO PHOTOGRAPHS**

PHOENIX IRON COMPANY, ROLLING MILL Pennsylvania Historic Bridges Recording Project - II N. of French Creek, W. of Fairview Av. Phoenixville Chester County Pennsylvania

HAER No. PA-493-C

Jet Lowe,	photographer,	summer	1999.
-----------	---------------	--------	-------

PA-493-C-1	ROLLING MILL COMPLEX, FROM NE.
PA-493-C-2	ELEVATION OF EAST END OF REMAINING NE CORNER OF MILL.
PA-493-C-3	EAST END OF SE CORNER OF ROLLING MILL.
PA-493-C-4	ROOF TRUSS DETAIL OF SE CORNER, NOTE PHOENIX COLUMN ROOF TRUSSES.
PA-493-C-5	SOUTH ELEVATION, FROM SE.
PA-493-C-6	MIDDLE SECTION OF SOUTH FACE OF MILL BUILDING, DEMOLISHED SHED IN MIDDLE FORMING BLANK BETWEEN BUILDINGS, RIGHT AND LEFT.
PA-493-C-7	DETAIL OF DEMOLITION IN ONE OF MIDDLE BAYS OF ROLLING MILL.
PA-493-C-8	SW CORNER OF MILL COMPLEX, FROM SW.
PA-493-C-9	SENSELESS DEMOLITION IN PROGRESS, SHOWING DESTRUCTION OF PERFECTLY DECENT AND RECYCLABLE MILL BUILDING. PROBLEM EXACERBATED BY HIGH VALUE OF SCRAP IRON.
PA-493-C-10	WESTERN FACADE OF MILL BUILDING, LOOKING EAST.
PA-493-C-11	DETAIL OF SAME, NOTE LARGE AND UNIQUE EXHAUST FAN AT ROOF PEAK.

## PHOENIX IRON COMPANY, ROLLING MILL HAER No. PA-493-C INDEX TO PHOTOGRAPHS (Page 2)

PA-493-C-12	NW CORNER OF ROLLING MILL, LOOKING EAST FROM BRIDGE OVER FRENCH CREEK.
PA-493-C-I3	GENERAL VIEW OF COMPLEX FROM NE CORNER, LOOKING WEST. PROBABLY GAS PRODUCING BUILDINGS AT RIGHT [VERIFY WITH JUSTIN].
PA-493-C-14	NORTH SIDE OF ROLLING MILL, LOOKING EAST AT DEMOLISHED SECTION.
PA-493-C-15	COLLAPSING WESTERN FACE AT NW CORNER OF ROLLING MILL.
PA-493-C-16	DETAIL OF ROOF TRUSSES SHOWING PHOENIX COLUMNS, NOTE STRUCTURAL PHOENIX COLUMN IN FOREGROUND.
PA-493-C-I7	INTERIOR OF ROLLING MILL AT NW QUADRANT OF STRUCTURE, NOTE STORED ROLLERS FOR VARIOUS STANDS.
PA-493-C-18	BASE OF PHOENIX COLUMN AT WESTERN END OF ROLLING MILL.
PA-493-C-19	ONE OF FEW INTACT AREAS OF ROLLING MILL, SHOWING EQUIPMENT LEFT OVER FROM PIPE AND TUBE MAKING IN THE 1970s AND '80s.
PA-493-C-20	HEATING OVENS IN SAME AREA AS ABOVE.
PA-493-C-21	INTERIOR OF ROOF, NW CORNER OF COMPLEX.
PA-493-C-22	DETAIL OF DOUBLED UP COLUMNS FOR ROOF SUPPORT.
PA-493-C-23	TRUSS DETAILS, NW CORNER OF ROLLING MILL.
PA-493-C-24	HEAVY-DUTY SUPPORT COLUMN WITHIN TUBE-MAKING COMPLEX.